SERVICE BULLETIN

M1614 **2023-11-03**

M1614: 2022 NIGHTSTER (RH975) SPEED SCREEN KIT

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2023-11-03	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that Speed Screen kit (Part No. 67700645DH) is replaced with (Part No. 67700706). The supplier is no longer able to produce Speed Screen (Part No. 67700645DH).

When replacing a speed screen on a 2022 Nightster (RH975), order kit (Part No. 67700706). This includes the speed screen and mounting bracket to convert the vehicle to a 2023 Nightster S (RH975S) **Post and Grommet** style assembly.

Vehicles Affected

2022: Nightster (RH975)

Markets Affected

All markets affected.

Part Numbers

Refer to Table 2.

Table 2. Part Numbers

Old Part No.	Item Description	New Part No.
67700645DH	Speed Screen kit	67700706

Required Dealer Action

Table 3.

Action Required	Resolution
NO ☑ YES ☐	**Non-Actionable:** This is for informational purposes only or a technical tip.

Install speed screen and bracket (Part No. 67700706) per the 2023 Sportster RH975 models service manual.




Figure 1. Old Part No.




Figure 2. New Part No.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									